

GEORGE BUTLER ASSOCIATES, INC.
Engineers · Architects

FIGURE C2-2
Existing Levels of Service
A.M. Peak Hour