
Paint on weathering steel has failed at expansion joints.
Bearing coming out
Pier 29 at west end of steel spans.
A4613
1-23-02
Bearing coming out

A4613 05-23-06
PIER 7 GDRS 3 & 7 NEOPRENE BRGS WORKING OUT.BE