

RFP 9-130327TV
Addendum 003

3) Due to windows and doors in the side walls we cannot use brace rods in side walls. I have not found any place showing 2 windposts?

ANSWER: The location of the windposts may vary depending on the manufacturer of the building. The manufacturer will place the windposts where they are engineered to be according to their specifications.

4) In specification section 13121, para. 2.4.C specifies a Galvalum finish for the maintenance building roof and the drawings for the storage building call for a Kynar finish on the roof of the storage building. Please clarify the finish type on the storage building roof.

ANSWER: Galvalum on both roofs.

5) Will a Clopay Model 3720 be acceptable for the sectional doors on this project?

ANSWER: YES

A SECOND Revised page 25 of the Skiles Building Drawings has been posted on our website. It connects the down spouts to the storm sewer.