



Route 94  
Interchange

Eastbound I-70  
Transverse Grooving  
2725 Ft Long

Begin transverse grooving  
3 thru lanes

Change to 6-lane grooving at gore point  
3 thru lanes + 3 ramp lanes

Groove gore area  
between thru lanes  
and ramp lanes

Change to 5-lane grooving  
3 thru lanes + 2 ramp lanes  
One ramp lane ends

End transverse grooving  
5 thru lanes

I-70

Fifth Street  
Interchange



Looking east on Eastbound I-70  
Approximate beginning location for  
3-lane grooving  
Exhibit A, Page 2 of 3



Looking east on Eastbound I-70  
Approximate beginning location for  
6-lane grooving at  
on-ramp from Route 94  
Exhibit A, Page 3 of 3